



Hydromission

Hydromission Sdn. Bhd. (535368-U)

HQ: 20, Lintang Beringin 6, Diamond Valley Industrial Park, Jalan Permatang Damar Laut, 11960 Bayan Lepas, Penang, Malaysia.

Branch: No. 72, Jalan E2/10, Taman Ehsan, Kepong, 52100 Kuala Lumpur, Malaysia.

Tel: 04-626 1187, 626 6973

Fax: 04-626 6975

HP: 012-422 1368 (Mr. K K Chang), 012-570 5211 (Ms. S F Foong)

Email: hydromission@gmail.com, mizutech88@gmail.com

Website: www.hydromission.com.my

Grease Trap Interceptor



Grease Trap Maintenance & Cleaning Services



Laboratory Water Analysis



FREE ON SITE ESTIMATES !!! CALL TO SCHEDULE OUR EVALUATION!!!
012- 422 1368 (Mr K K Chang)

Does your grease trap system face these problems?



- Oil & grease, fat and organics waste accumulate in the grease trap system and drain line causes clogging.
- Rotten egg odor surrounding the grease trap system due to presence of hydrogen sulphite (H_2S).
- Wastewater in grease trap system cannot free flowing.

If yes, call today for an on-site consultation. Hydromission Grease Trap System Maintenance Team providing turkey solutions for your grease trap systems: -

- ❖ Biological treatment to reduce clogging of grease trap systems.
- ❖ Neutralizes the rotten egg odor.
- ❖ Scoop the waste materials in the grease trap system to prevent drain line blocked.
- ❖ Wastewater from kitchen always kept in flowing.
- ❖ Provide on site analysis on each service.