



Hydromission

Hydromission Sdn. Bhd. (535368-U)

HQ: 20, Lintang Beringin 6, Diamond Valley Industrial Park, Jalan Permatang Damar Laut, 11960 Bayan Lepas, Penang, Malaysia.

Branch: No. 72, Jalan E2/10, Taman Ehsan, Kepong, 52100 Kuala Lumpur, Malaysia.

Tel: 04-626 1187, 626 6973

Fax: 04-626 6975

HP: 012-4221368 (Mr. K K Chang), 012-5705211 (Ms. S F Foong)

Email: hydromission@gmail.com, mizutech88@gmail.com

Website: www.hydromission.com.my

Cooling Tower Inspection

Cooling Tower Cleaning Services

Laboratory Water Analysis




FREE ON SITE ESTIMATES !!! CALL TO SCHEDULE OUR EVALUATION!!!
012- 422 1368 (Mr K K Chang)

Do your cooling towers face these problems?



Corrosion

- Metal wastage
- Plant breakdown




Scale

- Reduced heat transfer efficiency in the condenser tubes



Microbiological Fouling

- Greater risk of harmful organisms:
Legionella
Pneumophila



Suspended Solids

- Erosion leakages
- Increased microbial activity

If yes, call today for an on-site consultation. Hydromission Cooling Water Treatment can help to:-

- ❖ Inhibit corrosion, thereby prolonging the life of the system.
- ❖ Prevent scale formation and deposition, thus maintaining heat transfer efficiency.
- ❖ Prevent microbiological fouling, maintaining system efficiency and reducing health risks.
- ❖ Control chemical addition, so ensuring cost effective application of the programme.